


Corrosion Report



Equipment Location ID 0955-007-001
Equip. Location Descrip. C-1100 NO. 4 SIDECUT OUTLET

Remaining Life (Years) 3.31
Retirement Date 05/30/2015
Last Inspection Date 02/06/2012
Next Inspection Date 10/02/2013
Current Corrosion Rate 39.27

DP ID	MEAS METH	DP STAT	DP SZ	DT TYPE	BASE	MEAS 5	MEAS 4	MEAS 3	NEAR	LAST	MIN VALUE	CCR	REM LIFE
003.R	RT	A	8.00	ELL	0.270 04/88		0.280 04/95	0.270 05/98	0.280 04/01	0.180 02/12	0.100	9.22	8.68
004.R	RT	A	8.00	ELL	0.290 11/77	0.310 04/88	0.310 04/95	0.290 05/98	0.320 04/01	0.220 02/12	0.100	9.22	13.02
005.R	RT	A	10.00	PIPE	0.170 02/12						0.140	5.00	6.00
006.R	RT	A	10.00	PIPE	0.350 11/77	0.330 05/92	0.320 05/98	0.340 04/00	0.340 04/01	0.270 02/12	0.140	6.45	20.15
007.R	RT	A	10.00	ELL	0.210 02/12						0.140	5.00	14.00
008.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.322 10/02	0.170 02/12	0.100	16.29	4.30
009.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.200 11/11	0.260 02/12	0.100	1.72	93.13
010.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.240 11/11	0.240 02/12	0.100	2.27	61.62
011.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.190 11/11	0.290 02/12	0.140	0.89	169.30
012.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.290 11/11	0.350 02/12	0.140	0.00	∞
013.R	RT	A	8.00	PIPE	0.322 01/76			0.322 10/02	0.280 11/11	0.270 02/12	0.140	39.27	3.31
014.R	RT	A	8.00	PIPE	0.270 02/12						0.140	5.00	26.00
015.R	RT	A	8.00	PIPE	0.270 02/12						0.140	5.00	26.00
016.R	RT	A	8.00	PIPE	0.290 02/12						0.140	5.00	30.00
017.R	RT	A	8.00	PIPE	0.210 02/12						0.140	5.00	14.00
018.R	RT	A	8.00	PIPE	0.200 02/12						0.140	5.00	12.00
019.R	RT	A	8.00	PIPE	0.180 02/12						0.140	5.00	8.00





History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	11/5/2011	Date Available:	11/05/2011
History Brief Date:	10/20/2011	History Brief ID:	VI-1110247836
Event Type:	Inspection	In- Service Date:	11/05/2011
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	10/20/2011
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	API 570 inspection		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Corrosion	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	TBEA
Save:		Inspected By:	TBEA

Findings:

<u>PCA ID:</u>	PCA-002064093	<u>Condition:</u>	
<u>Inspectable:</u>	GENERAL	<u>Action:</u>	
<u>Sub Item:</u>		<u>Location:</u>	
<u>Part:</u>		<u>Damage Mechanism:</u>	
<u>Discussion:</u>		<u>PCA Work Order No :</u>	

Reliability Comments:

Information

Piping circuit inspected for sulfidation corrosion.

Corrosion rate at TML 9E is based using the nominal thickness in 2002. long term corrosion rate provides a RL of 11 years with a half life inspection during the 2016 S/D.

corrosion rate at TML 11B is based on a nominal thickness in 2002 long term corrosion rate provides a remaining life of 11 years with a half life inspection during 2016 S/D.

calculated T-min provided by DED

For the P-1149 suction piping t(min):

1. 8 inch pipe:
 - a. Pressure t(min) = 0.018 inch
 - b. Structural t(min) = 0.036 inch
2. 10 inch pipe:
 - a. Pressure t(min) = 0.022 inch
 - b. Structural t(min) = 0.036 inch



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

So, I would use the 0.036 inch as the ultimate t_{min} for this section of pipe. If piping get below 0.100 inches, we should consider some sort of clamp or wrap. After talking to inspections, this might also be a good location for a corrosion probe.

Hope this helps,

If you have any questions, please do not hesitate to contact me.

Thanks for the help,
Patrick Murphy



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	8/22/2007	Date Available:	08/22/2007
History Brief Date:	04/10/2012	History Brief ID:	VI-1204254535
Event Type:	Inspection	In- Service Date:	08/22/2007
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	08/22/2007
Asset Type:	221	Inspection Type:	EVI
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	RFMS CUI Project		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Corrosion	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	CSAA
Save:		Inspected By:	CSAA

Findings:

PCA ID:
Inspectable:
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No :

Reliability Comments:

DELUGE AREA? Cooling Tower? Moderate CUI noted. RT 2 locations.



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	10/15/2002	Date Available:	
History Brief Date:	10/15/2002	History Brief ID:	HB-0210080308
Event Type:	Inspection	In- Service Date:	
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	Piping u/s & d/s Of TML's RT'd For Hot H2S Corr, 1 Ell Corr, Scale Noted		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	JMJG
Save:		Inspected By:	

Findings:

<u>PCA ID:</u>	PCA-002021753	<u>Condition:</u>	
<u>Inspectable:</u>	GENERAL	<u>Action:</u>	Not Resolved
<u>Sub Item:</u>		<u>Location:</u>	
<u>Part:</u>	PIPE WALL	<u>Damage Mechanism:</u>	1
<u>Discussion:</u>		<u>PCA Work Order No :</u>	

Reliability Comments:

The straight run piping on the existing (mostly ells) TMLs was RT'd to look for hot H2S corrosion. The corrosion can occur on CS piping above 550 deg F (this line runs up to above 600 deg F). Only one section of piping (downstream of TML # 3) had internal corrosion and pitting, the piping has lost approximately 1/3 of it's original wall thickness (nominal is 0.322 for 8" Sch 40 piping). The 6" suction header branch connection has ~ 2" of scale on the bottom below the 3" pump-out piping connection. Due to the corroded ell found and the service conditions, the piping will be recommended for replacement during the next scheduled shutdown. -jmg 10/15/2002 4:13:18 PM



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	5/22/1998	Date Available:	05/22/1998
History Brief Date:	05/22/1998	History Brief ID:	RPR-2023858
Event Type:	Information	In- Service Date:	05/22/1998
Equipment ID:	0955-007-001	Critical:	
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	98 OSI INSP		

Reliability Analysis:

Event Type:	Information	Worked Performed By:	Chevron - General
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Other
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	DANM
Save:		Inspected By:	

Findings:

PCA ID:
Inspectable:
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No.:

Reliability Comments:



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	11/5/2011	Date Available:	11/05/2011
History Brief Date:	10/20/2011	History Brief ID:	VI-1110247836
Event Type:	Inspection	In- Service Date:	11/05/2011
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	10/20/2011
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	API 570 inspection		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Corrosion	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	TBEA
Save:		Inspected By:	TBEA

Findings:

PCA ID: PCA-002064093
Inspectable: GENERAL
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No :

Reliability Comments:

Information
Piping circuit inspected for sulfidation corrosion.
Corrosion rate at TML 9E is based using the nominal thickness in 2002. long term corrosion rate provides a RL of 11 years with a half life inspection during the 2016 S/D.
corrosion rate at TML 11B is based on a nominal thickness in 2002 long term corrosion rate provides a remaining life of 11 years with a half life inspection during 2016 S/D.

calculated T-min provided by DED

For the P-1149 suction piping t(min):

1. 8 inch pipe:
 - a. Pressure t(min) = 0.018 inch
 - b. Structural t(min) = 0.036 inch
2. 10 inch pipe:
 - a. Pressure t(min) = 0.022 inch
 - b. Structural t(min) = 0.036 inch



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

So, I would use the 0.036 inch as the ultimate t_{min} for this section of pipe. If piping get below 0.100 inches, we should consider some sort of clamp or wrap. After talking to inspections, this might also be a good location for a corrosion probe.

Hope this helps,

If you have any questions, please do not hesitate to contact me.

Thanks for the help,
Patrick Murphy



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	8/22/2007	Date Available:	08/22/2007
History Brief Date:	04/10/2012	History Brief ID:	VI-1204254535
Event Type:	Inspection	In- Service Date:	08/22/2007
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	08/22/2007
Asset Type:	221	Inspection Type:	EVI
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	RFMS CUI Project		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Corrosion	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	CSAA
Save:		Inspected By:	CSAA

Findings:

PCA ID:

Inspectable:

Sub Item:

Part:

Discussion:

Condition:

Action:

Location:

Damage Mechanism:

PCA Work Order No :

Reliability Comments:

DELUGE AREA? Cooling Tower? Moderate CUI noted. RT 2 locations.



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	10/15/2002	Date Available:	
History Brief Date:	10/15/2002	History Brief ID:	HB-0210080308
Event Type:	Inspection	In- Service Date:	
Equipment ID:	0955-007-001	Critical:	L
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRRI00281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	Piping u/s & d/s Of TML's RT'd For Hot H2S Corr, 1 Ell Corr, Scale Noted		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Reliability
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	JMJG
Save:		Inspected By:	

Findings:

<u>PCA ID:</u>	PCA-002021753	<u>Condition:</u>	
<u>Inspectable:</u>	GENERAL	<u>Action:</u>	Not Resolved
<u>Sub Item:</u>		<u>Location:</u>	
<u>Part:</u>	PIPE WALL	<u>Damage Mechanism:</u>	1
<u>Discussion:</u>		<u>PCA Work Order No :</u>	

Reliability Comments:

The straight run piping on the existing (mostly ells) TMLs was RT'd to look for hot H2S corrosion. The corrosion can occur on CS piping above 550 deg F (this line runs up to above 600 deg F). Only one section of piping (downstream of TML # 3) had internal corrosion and pitting, the piping has lost approximately 1/3 of it's original wall thickness (nominal is 0.322 for 8" Sch 40 piping). The 6" suction header branch connection has ~ 2" of scale on the bottom below the 3" pump-out piping connection. Due to the corroded ell found and the service conditions, the piping will be recommended for replacement during the next scheduled shutdown. -jmg 10/15/2002 4:13:18 PM



History Brief

For Location ID: 0955-007-001 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	5/22/1998	Date Available:	05/22/1998
History Brief Date:	05/22/1998	History Brief ID:	RPR-2023858
Event Type:	Information	In- Service Date:	05/22/1998
Equipment ID:	0955-007-001	Critical:	
Asset ID:	0000110906	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	98 OSI INSP		

Reliability Analysis:

Event Type:	Information	Worked Performed By:	Chevron - General
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Other
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	DANM
Save:		Inspected By:	

Findings:

<u>PCA ID:</u>	<u>Condition:</u>
<u>Inspectable:</u>	<u>Action:</u>
<u>Sub Item:</u>	<u>Location:</u>
<u>Part:</u>	<u>Damage Mechanism:</u>
<u>Discussion:</u>	<u>PCA Work Order No :</u>

Reliability Comments: